(November 1983) (Formerly 9-331)	DEPARTMENT O		SUBMIT IN TRIPLICA (Other instruct on verse side)	Expires	Bureau No. 1004-0135 August 31, 1985 IGNATION AND SERIAL NO.	
SUN (Do not use this	BUREAC JF LA IDRY NOTICES AN form for proposals to drill Use "APPLICATION FOR	ND MANAGEMENT ND REPORTS OF to deepen or plug back PERMIT—" for such page.	N WELLS k to a different reservoir.	LC-0294		
1.		- Division for such prop	RECEIVED	7. UNIT AGRE		
WELL WELL GAS	OTHER			Ŀ		
2. NAME OF OPERATOR				Skelly Un	ALE WAND	
Texaco Produc	eing Inc.		OCT 23 '90	Skelly U	nit	
P O Roy 730	Takka mar	- 000/0		9. WELL NO.		
4. LOCATION OF WELL (I	Hobbs, New Mexi Report location clearly and in	CO 8824U 2	O. G. D.	152		
At surrace			ARTESIA, OFFICE		POOL, OR WILDCAT	
Letter L, 183	30' FSL & FWL 🔑	A.C. 7 (97 <u>)</u>		11. anc., T., 2	Ven Rivers M., OR BLE. AND OR ARMA	
14. PERMIT NO.	15. BLEVA	rions (Show whether DF, E		Sec 15,T-	-17-S, R-31-E	
	3	65' GL	, ur. etc.)		R PARISE 18. STATE	
16.				Eddy	NM	
,	Check Appropriate	box to Indicate Nat	ure of Notice, Report, o	or Other Data		
	NOTICE OF INTENTION TO:		SUBSEQUENT EXPORT OF:			
TEST WATER SHUT-O			WATER SHUT-OFF	BEI	PAIRING WELL	
SHOOT OR ACIDIZE	MELTIPLE CO	MPI.ETE	FRACTURE TREATMENT	ALI	FERING CASING	
REPAIR WELL	ARANDON* CHANGE PLAN		SHOOTING OR ACIDIZING	ABA	NDONMENT* X	
(Other)			(Other)	ults of multiple con	Dietion on Well	
17. DESCRIBE PROPOSED OF proposed work. If nent to this work.)	completed operations (Clewell is directionally drilled, 9-26-90 thru 9-	early state all pertinent d give subsurface location -28-90	Completion or Reco etails, and give pertinent da s and measured and true ver	carpletion Report and test including estimates, inc	i Log form.) ated date of starting any markers and sones perti-	
2. POH w/ tbg	w/pump and rods	install BOP			0 frn n	
	et on 2 3/8 tbg	0 00/51			Post ID-2 11-9-90	
4. Pmp 25 sx on	top of retainer	set @ 2245'			11-7-90 P&A	
 Load hole w/ 	salt gel mud				[7/]	
6. Pull up hole	and spot plug f	/ 1805-1536 WO	С			
/. Tag plug, pu	11 up & spot 25 s	sx f/ 635-4351	UOC			
9. Cut off & se	94' spot plug 7 s	sx 50' to surfa	ce		~c o	
out off a se	c marker.				ARE	
				sa sa		
					= 3 5	
					<u>ಪ</u> ್ಪ <u>ಹ</u>	
				·-	<i>7</i>	
	•					
18. I hereby certify that	the foregoing is true and con	rrect				
SIGNED KICKA	d Neder	TITLEEngi	ineering Technicia	an	10-16-90	
(This space for Feder	al or State office use)			DATE	0 10 30	
APPROVED BYCONDITIONS OF AP		TITLE		DATE _/	10 19.90	
LALLY SELECTION	one usida. Tendi One one escad.	*See Instructions on	Reverse Side			

*See Instructions on Reverse Side