

HALLIBURTON DIVISION LABORATORY
HALLIBURTON SERVICES
MIDLAND DIVISION
HOBBS, NEW MEXICO 88240

LABORATORY WATER ANALYSIS


No. W81-1168

To General American Oil Company

Date 12-28-81

Box 128

Loco Hills, New Mexico



This report is the property of Halliburton Company and neither it nor any part thereof nor a copy thereof is to be published or disclosed without first securing the express written approval of laboratory management; it may however, be used in the course of regular business operations by any person or concern and employees thereof receiving such report from Halliburton Company.

Submitted by _____ Date Rec. 12-28-81

Well No. Green "B" #12 Depth 10,666' Formation Morrow

County Eddy Field S. Empire Source DST #1

	<u>Top of Recovery</u>	<u>Middle of Recovery</u>	<u>Bottom of Recovery</u>
Resistivity	<u>0.077 @ 74°F.</u>	<u>0.081 @ 74°F.</u>	<u>0.086 @ 74°F.</u>
Specific Gravity	_____	_____	_____
pH	_____	_____	_____
Calcium (Ca)	_____	_____	_____ *MPL
Magnesium (Mg)	_____	_____	_____
Chlorides (Cl)	<u>80,000</u>	<u>79,000</u>	<u>79,000</u>
Sulfates (SO ₄)	_____	_____	_____
Bicarbonates (HCO ₃)	_____	_____	_____
Soluble Iron (Fe)	_____	_____	_____

Pit Sample - Res. @ 74°F. - 0.077 Chlorides, mpl - 80,000

Remarks:

*Milligrams per liter

Respectfully submitted,

Analyst: Brewer

HALLIBURTON COMPANY

cc:

By: W. Z. Brewer

CHEMIST

NOTICE

THIS REPORT IS LIMITED TO THE DESCRIBED SAMPLE TESTED. ANY USER OF THIS REPORT AGREES THAT HALLIBURTON SHALL NOT BE LIABLE FOR ANY LOSS OR DAMAGE, WHETHER IT BE TO ACT OR OMISSION, RESULTING FROM SUCH REPORT OR ITS USE.

