Form 3160-5 (November 1994)

· ·	II C	s. Di asicii	
3 1	st	1^	
	_	FORM APPROVED	
	V! (	36210-2834 OMB No. 1004-0135	

UNITED STATES Ar. DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NM-//34696 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other Instructions on reverse side Type of Well X Oil Well Gas Well Gother 8. Well Name and No. VOLA FED. Name of Operator Ray Westall RECEIVED 9. API Well No. 30-015-24050 Phone No. (include area code) A Address P. O. Box 4, Loco Hills, .10. Field and Pool, or Exploratory Area Grayburg Jackson-7R-QN-GB Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State FSL & 2180' 660' 1, 17S, 31E Sec EDDY, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION ☐ Production (Start/Resume) ☐ Water Shut-Off Deepen Acidize Notice of Intent Well Integrity Fracture Treat ☐ Reclamation Alter Casing \*\*D Other Varience Subsequent Report New Construction Recomplete Casing Repair Request Plug and Abandon Temporarily Abandon Change Plans Final Abandonment Notice Plug Back Water Disposal Convert to Injection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) OSO #4 Section III. C. 1. a. requires that each sales tank shall be equipped with a pressure vacuum thief hatch and vent line valve. The purpose of the requirement is to prevent loss of product at low volume and pressure or by flashing of light ends in high gravity oil. A fluid with an API gravity below 36 degrees will not have a significant flashing of light ends within the normal temperature range. The loss of gas from a low volume facility would be insignificant if the sales tank is vented to the atmosphere. OSO #4 provides for granting requests for a variance from the minimum standards. Oil produced from this lease has a gravity of 34.4 and the lease produces 4 barrels of oil per day.

14. I hereby certify that the foregoing is true and correct  Name (Printed Typed)  CS37 ( a Pando Jessica Pando Signature	Title Production Clerk Date
	1/12/98
THIS SPACE FOR FEDE	RAL OR STATE OFFICE USE
Approved by ORIG. SCD.) DAVID R. GLASS	PETRÖLEUM ENGINEER Date JAN 2 3 1998
Conditions of approval, if any, are attached. Approval of this notice does not we certify that the applicant holds legal or equitable title to those rights in the subjection would entitle the applicant to conduct operations thereon.	arrant or Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.