Fill out only Sections I. II. III, and VI for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.

(Tille)

(Date)

9/13/82

TRAFALGAR DRILLING COMPANY

INCLINATION REPORT

		~	-		
W W WE PRESIDEN PH 915 600	EIR	122 NGRTH N. 6. T P.O. BOX 549 7	FALGAR DRILLING COMPANY 122-NGRTH-N61, P.O. BOX.5497 - 4396 MIDLAND, TEXAS 79704		P A CENED
J. Cleo Thompson Oil Company 4500 Republic National Bank Tower Dallas, Texas 75201			Hoover State #3 Eddy County, N.M.		
	,	INCLINATION REP	ORT		·F
trasured Dep	th Course Length (Hundreds of feet)	Angle of Inclination (Degrees)	Displacement per Hundred of Feet(Sine of Anglex100)	Course Displace- ment (feet)	Accumu- lative Displace- ment(feet)
261 520 960 1451 1900	261 259 440 490 510	3/4 1-1/2 1 3/4 1/2	1.31 61 1.75 31 .87	3.42 6.79 7.70 6.42 4.44	3.42 10.21 17.91 24.33 28.77
. 445 2934 253	488 486 316	1/2 1/2 1/2 3/4	.67 .87 1.31	4.25 4.23 4.14	33.02 37.25 41.39

Accumulative total displacement of well bore at total depth of 3250 feet = 41.39 feet.

inclination measurements were made in drill pipe.

ĭ

Was the subject well at any time intentionally deviated from the vertical in any manner whatsoever? NO

Roy Kecter, Trilling Superintendent

STATE OF TEXAS

TOUNTY OF MIDLAND Y

BEFUFF ME this day personally appeared Roy Keefer, the person whose signature appears above who by me being duly sworn upon oath says the above statements are true and correct.

Silescribed and sworn to before me this 25th day of Asgust, 1982.

Joan Tradale Notary Public, Midland County, Texas