

COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
NOV 29 1984
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-	7. Unit Agreement Name
2. Name of Operator Beach Exploration, Inc.	8. Farm or Lease Name Arco State
3. Address of Operator 800 N. Marienfeld Suite 200 Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>2310</u> FEET FROM THE <u>West</u> LINE AND <u>330</u> FEET FROM THE <u>South</u> LINE, SECTION <u>9</u> TOWNSHIP <u>17S</u> RANGE <u>29 E</u> N.M.P.M.	10. Field and Pool, or Whiccat Cave Grbg (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 3577.0	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @2200' with 35' Cement Cap.
Set 25 Sx Plug @ 2050'
Set 25 Sx Plug @ 450'
Set 10 Sx Plug @ Surface

Put dry hole marker in surface plug with operator's name, well name and number and legal description of location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. F. Jones TITLE Production Sup. DATE 11-26-84

APPROVED BY Mike Williams OIL AND GAS INSPECTOR
DATE DEC - 5 1984
CONDITIONS OF APPROVAL, IF ANY: Plugging