


NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.B.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>



Form C-103
Revised 10-1-79

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Beach Exploration, Inc. ✓	8. Farm or Lease Name Conoco State
3. Address of Operator 800 N. Marienfeld Suite 200 Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER J, 1650 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 9 TOWNSHIP 17S RANGE 29 E NMPM.	10. Field and Pool, or Wildcat Cave Grby (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 3569.6	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 1900' with 35' Cement cap.
Set 25 Sx plug @ 1700'
Set 25 Sx plug @ 450'
Set 10 Sx plug @ Surface

Put dry hole marker in surface plug with operators name, well name, and number, and legal description of location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. F. Jones TITLE Production Sup. DATE 11-26-84

APPROVED BY _____ ORIGINAL SIGNED BY LARRY BROOKS GEOLOGIST - NMOC TITLE _____ DATE DEC 7 1984

CONDITIONS OF APPROVAL, IF ANY:

