

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P.O. BOX 2088
SANTA FE, NEW MEXICO 87501
APR 11 1984
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E-10163

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator J.E.M. Resources ✓ 3. Address of Operator P.O. Box 2938 Ruidoso, N.M. 88345 4. Location of Well UNIT LETTER <u>G</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>5</u> TOWNSHIP <u>17S</u> RANGE <u>29E</u> N.M.P.M. 15. Elevation (Show whether DF, RT, GR, etc.) 3613 GR	7. Unit Agreement Name C.P.U. 8. Farm or Lease Name Cave Pool Unit 9. Well No. 58 10. Field and Pool, or Wildcat Cave GB/SA 12. County Eddy
---	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-28-84 Well pumping 5-7 BOPD +20 MCFG

3-29-84 Perf Grayburg 2187-2331 w/36.40 cal shots Acid w/3250 gal 15% HCL inj 5.1 BPM @ 2700# ISPD 1300# 15 min. 1250#.

3-30-84 Frac 2187-2331 w/ 40,000 gal gel KCL wtr + 52,00# 20/40 sd. inj 59 BPM @ 1750# ISDP 1150# 15 min 975#

3-31-84 Put well back on production

4-5-84 Well making 10 BOPD + 90 MCFG

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Geologist DATE 4-11-84
APPROVED BY Randy Brooks TITLE Geologist DATE 4-11-84