

UNITED STATES BLM & CAD/CBAD
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.

6. LEASE DESIGNATION AND SERIAL NO.

NM 14847

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Green-Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

A I D - 4 SR

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 19-T17S-R29E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Fred Pool Drilling, Inc.

3. ADDRESS OF OPERATOR

P.O. Box 1393, Roswell,

N. M. 8820 OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1219' FWL 1700' FNL SE/4 NW/4

14. PERMIT NO.

30-015-25643

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3696 Gr

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Intention to Plug and Abandon:

Plug and abandon procedure as per Mr. Pitschke of Bureau of Land Management, verbal 9-5-86.


1.) Cement plug from 1930' - 1812', tag

2.) Cement plug from 864' - 764',

3.) 100' plug from 432' - 332'. (Shoe)

4.) 50' plug at surface.

CIBP at 3580' with 35 sx cement.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Vice President

DATE 9-8-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: