

07/09/99 WASH F/+/-10737 T/1 47', STOP MKNG HOLE, COOH W/TBG & TLS, R. JVE 1 JT TBG & R NIP F/WASH PIPE, LE 1 JT WASH PIPE, GIH W/NEW SHOE, WASH PIPE, JARS, COLLARS & TBG.

07/10/99 FIN GIH, WKOVER FISH, MILL 4', TLS FELL 1' & TRQD UP, PU T/FREE TLS, WOULN'T GO DWN, SET 3 PTS ON FISH, NO TRQ, CIRC CLN, SOOH W/FISH IN WASH PIPE, LOST FISH +/-1800' OF BTM, WO OVERSHOT, GIH W/OVERSHOT, BMPR SUB, JARS, COLLARS & TBG, CATCH FISH, SIDS DUE T/WEATHER.

07/11/99 COOH W/FISH 10' TBG SUB, PKR, 1 JT TP, 2.25" R NIPL, LD COLLARS, BMPR SUB & JARS, WO ANNUL BOP, NU ANNUL ON TOP BOP, GIH W/NOTCHED COLLAR, 1 JT 2-7/8" TBG, 2.25" F NIPL W/RETRIEV CK VLV & +/-3500' OF 2-7/8" TBG, MIRU DAVIS TL AIR UNIT, GIH W/10 STDS TBG BLOWNG DRY W/AIR UNIT UNTIL REACHING +/-5350'.

07/12/99 BLOW WTR OUT WELL F/+/-5350 T/10100'.

07/13/99 BLOW OUT WTR F/+/-10100 T/+/-10820', TAG SAND, WASH SAND T/+/-10828', GET STUCK, WK FREE, WK BK T/10828', CIRC AIR T/CLN UP.

07/14/99 OPEN UP W/800# ON BK SIDE, VENT DWN, CO F/+/-10930 - +/-11121', SWP CLN, VENT DWN TBG, RD AIR RET LN & STRPR, ND BOP, FLNG UP TREE, MIRU JSI, GIH FISH DWN HOLE CK, RD JSI.

07/15/99 RD DDU, CLN LOC, MO, OPEN UP WELL W/780# ON TBG, CRACK CHOKE & OVER RNG SALES METER, WO PLATE CHG, OPEN UP @ +/-950M W/765# ON TBG, ADJUST RATE AS PRESSURE FELL, LEAVE @ +900m W/440# ON TBG.

07/16/99 FLOW 364 M W/TBG PRESS START OUT @ 790# DROP T/360# TEMP DROP F/REPORT

07/22/99 07/18/99 733 MCF @ 110# ON TBG
 07/20/99 758 MCF @ 100# ON TBG
 07/22/99 775 MCF @ 100# ON TBG
 GOING DOWN SALES LINE
COMPLETE DROP F/REPORT