

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-029435-B	
2. NAME OF OPERATOR Hondo Oil & Gas Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 2208, Roswell, NM 88202		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 660' FWL		8. FARM OR LEASE NAME J. L. Keel "B" Federal	
14. PERMIT NO.		9. WELL NO. 40	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3771' GR		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson	
		11. SEC., T., S., M., OR BLK. AND SURVEY OR ABMA Sec. 6-T17S-R31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8/4/88 Perforated 3340, 59, 68, 75, 80, 95, 3409, 20, 22, 29, 32, 39, 45, 48, 52, 64, 67, 72, 76 & 83' w/l JSPF. Acidized perfs. 3340-3483' w/2000 gal. 15% NE-FE + 30 ball sealers.

8/5/88 Frac'd w/40,000 gal. 30# cross-linked gel + 82,000# 20-40 sand. Set frac bomb and pressured up to 2000 psi. Perforated 2826, 29, 53, 59, 69, 77, 83, 88, 97, 2906, 18, 28, 34, 38, 41, 51, 70, 75, 78, 90, 92, 3003, 06, 09, 17, 21, 32, 34, 41, 44, 53, 57, 65, 67, 72, 76, 79, 84, 88, 95, 97, 3100, 24, 34, 45, 68, 84, 99, 3215, 22, 24 & 34' w/l JSPF. Frac'd w/80,000 gal. 30# cross-linked gel + 164,000# 20-40 sand + ball sealers.

8/7/88 Pulled frac bomb. Left well flowing back to frac tanks.

RECEIVED

AUG 9 10 47 AM '88

18. I hereby certify that the foregoing is true and correct

SIGNED William D. Fulton TITLE Engineer

DATE 8/9/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

SSX