

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		OCT 27 11 45 AM '88		UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Hondo Oil & Gas Company		CARLSBAD AREA OFFICE		3. FARM OR LEASE NAME H. E. West "B"	
3. ADDRESS OF OPERATOR P. O. Box 2208, Roswell, NM 88202				9. WELL NO. 34	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FEL		NOV 23 '88		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3919' GL		12. COUNTY OR PARISH Eddy	
		O. C. D. ARYESIA OFFICE		13. STATE NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input checked="" type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

10/11-17/88 Perforated 3616-3802' with 47 holes. Acidized 3616-3802' with 3000 gal. 15% NEFE acid. Frac'd 3616-3802' with 50,000# gal. 30# crosslinked gel + 34,000# 20-40 sand. Flowed and swabbed well back. Reacidized 3616-3802' with 2000 gal. 15% NEFE acid. Swabbed well back.

10/18-19/88 Reperforated 3616-3735' with 16 shots. Frac'd 3616-3802' with 50,000 gal. 30# crosslinked gel + 96,000# 20-40 sand. Flowed well back to clean up.

ACCEPTED FOR RECORD

NOV 21 1988

EB
CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Ron Brown

TITLE

Engineer

DATE

10/25/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side