

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP DATE
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

2158

5. LEASE DESIGNATION AND SERIAL NO.

C-029426-B

6. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Hondo Oil & Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 2208, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FNL & 660' FEL

RECEIVED

DEC 12 '88

O. C. D.

ARTESIA, OFFICE

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3896' GL

8. FARM OR LEASE NAME

H. E. West "B"

9. WELL NO.

36

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 9-T17S-R31E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11/04/88 Perforated 3267-3462' with 81 shots. Acidized 3267-3462' with 6000 gal. 15% NEFE acid. Flowed and swabbed well back.
11/05/88 Frac'd 3267-3462' with 80,000 gal. cross-linked gel + 160,000# sand. Swabbed well back.
11/09/88 Perforated 3199-3234' with 23 shots. Acidized 3199-3234' with 3000 gal. 15% NEFE acid. Flowed well back.
11/10/88 Frac'd 3199-3234' with 24,000 gal. cross-linked gel + 36,000# sand. Flowed and swabbed well back.

18. I hereby certify that the foregoing is true and correct

SIGNED Lisa Bohannon

TITLE Engineering Technician

DATE 11/14/88

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

DEC 6 1988

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO