

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
reverse side)

FE-
re-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-029426-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Hondo Oil & Gas Company

3. ADDRESS OF OPERATOR
P. O. Box 2208, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
2105' FNL & 660' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3932' GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
H. E. West "B"

9. WELL NO.
42

10. FIELD AND POOL, OR WILDCAT
Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 10-T17S-R31E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2/16/89 Set CIBP @ 3800'. Perforated 3614-3791' with 85 shots. Acidized 3614-3791' with 6000 gal. 15% NEFE acid. Swabbed well back.

2/17/89 Frac'd 3614-3791' with 60,000 gal. 30# gelled water + 120,000# 20-40 sand. Swabbed and flowed well back.

2/22/89 Perforated 3546-3599' with 35 shots. Acidized 3546-3599' with 3000 gal. 15% NEFE acid. Flowed and swabbed well back.

RECEIVED
FEB 28 10 41 AM '89
CARL AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Engineer

DATE 2/27/89

(This space for Federal or State office use)

APPROVED BY

(ORIG. SGD.) DAVID R. GLASS

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

(CARL AREA, NEW MEXICO) *See Instructions on Reverse Side