

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE
(Other instructions
verse side)

TE-
re-

form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-029426-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Hondo Oil & Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 2208, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

660' FSL & 760' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3814'

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

H. E. West "B"

9. WELL NO.

43

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 9-T17S-R31E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2/20/89 Perforated 3586-3673' with 37 shots.

2/23/89 Acidized 3586-3673' with 2000 gal. 15% NEFE acid. Flowed and swabbed well back.

2/24/89 Re-acidized 3586-3673' with 6000 gal. 20% CRA acid. Swabbed well back.

2/25/89 Perforated 3371-3553' with 70 shots. Acidized 3371-3553' with 6000 gal. 15% NEFE acid. Swabbed well back.

2/26/89 Frac'd 3371-3553' with 60,000 gal. XL-30 Borate gel + 120,000# 20-40 sand. Flowed and swabbed well back.

3/01/89 Perforated 3141-3324' with 76 holes. Acidized 3141-3324' with 6000 gal. 15% NEFE acid. Flowed and swabbed well back.

3/04/89 Frac'd 3141-3324' with 60,000 gal. x-linked gel + 130,000# 20-40 sand. Flowed well back.

NOTE: Please disregard the sundry notice on this well dated 2/27/89. These are the correct perforations and corresponding acid and frac jobs.

18. I hereby certify that the foregoing is true and correct

SIGNED Nisa Johanson

TITLE Engineering Technician

DATE 3/10/89

(This space for Federal or State office use)

APPROVED BY (ONIG. SGD) DAVID R. GLASS

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

See Instructions on Reverse Side