	UNITED STATES RTMEN OF THE INTER REAU OF LAND MANAGEMEN	•		
	OTICES AND REPORTS reposals to drill or to deepen or plug LICATION FOR PERMIT " for such		6. IF INDIAN, ALLOTTER OR TRIBE NAME	
OIL X GAS WELL OTHE	R		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Hondo Oil & Gas Com 3. ADDRESS OF OPERATOR	pany /	RECEIVED	8. FARM OR LEASE NAME J. L. Keel "B" 9. WELL NO.	
P. O. Box 2208, Ros 1. LOCATION OF WELL (Report location See also space 17 below.) At surface 660' FNL & 660' FEL	on clearly and in accordance with an	y State regultements. MAR 16 '89	44 10. FIELD AND POOL, OR WILDCAT Grayburg Jackson / 11. 580., T. B., M., OR BLE. AND	
OGG THE GOOD THE		O. C. D. ARTESIA, OFFICE	SURVEY OR ARMA	
14. PERMIT NO.	15. PLEVATIONS (Show whether to	F, RT, GR, etc.)	Sec.5-T17S-R31E 12. COUNTY OR PARISH 13. STATE	
16. Check	Appropriate Box To Indicate		Other Data	
		UENT REPORT OF:		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dir nent to this work.) **	PULL OF ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS POPERATION: (Clearly state all pertine rectionally drilled, give subsurface loc	SHOOTING OR ACIDIZING (Other) (NOTE: Report result Completion or Recons	BEPAIRING WELL ALTERING CASING ABANDONMENT* s of multiple completion on Well pletion Report and Log form.) s, including estimated date of starting any cal depths for all markers and zones perti-	
2/20/89	Perforated 3641-3865'	with 69 shots.		
3/03/89	Acidized 3641-3865' w Swabbed well back.	idized 3641-3865' with 6000 gal. 15% NEFE acid. abbed well back.		
3/04/89	Frac'c 3641-3865' with 60,000 gal. cross-linked gel + 120,000# 20-40 sand. Flowed well back.			
	·			
			T I	
			_ Cn	
			IVED	
			- 63 - 63	
18. I hereby certify that the foregoin	4 " " 17			
signed) (Se Silve	and TITLE E	ngineering Technician	DATE 3/6/89	
(This space for Federal or State APPROVED BY (ORIG. COD) CONDITIONS OF APPROVAL, I	DAVID R CIASITLE		DATE	

*See Instructions on Reverse Side