

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	IOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Rustler	489	672	
Salado	672	1622	
Tansill	1622	1776	
Yates	1776	2087	
Seven Rivers	2087	2702	
Queen Sands	2702	2732	
(Artesia)			
Grayburg	3128	3440	
San Andres	3440	4280 (TID)	
		DEPTH	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)
		3714'-3801'	Acidize w/3625 gals 15% HCl acid.
		3572'-3604'	Acidized w/2075 gals 15% HCl acid.
		3572'-3801'	Frac'd w/9500 gals gel + 25,500# 20/40 Brady sand.
		3189'-3435'	Acidized w/2500 gals 15% HCl acid. Frac'd w/28,000 gals gel + 80,000# 20/40 Brady sand + 24,000# resin coated sand.

38.

GEOLOGIC MARKERS

NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH