

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	403	558	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front) 16,000# resin coated sand. Acidized w/1800 gals 15% HCl acid. Frac'd w/32,000 gals x-linked gel + 85,000# 20/40 Brady sand + 24,000# resin coated sand.			
Salado	558	1326				
Tansill	1326	1481				
Yates	1481	1777				
Seven Rivers	1777	2376				
Queen	2376	2794				
Grayburg	2794	3100				
San Andres	3100	4000 (TD)				
		DEPTH				
		2929' - 3079'				