

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	342	500	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)			
Salado	500	1418				
Tansill	1418	1572				
Yates	1572	1873				
Seven Rivers	1873	2503				
Queen	2503	2903				
Grayburg	2903	3213				
San Andres	3213	4070 (TD)				
		DEPTH				
		3513'-3709'				
		3300'-3433'				
		2987'-3254'				