

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	394	515	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)			
Salado	515	1342				
Tansill	1342	1492				
Yates	1492	1792				
Seven Rivers	1792	2394				
Queen	2394	2811				
Grayburg	2811	3116				
San Andres	3116	4010 (TD)				
		DEPTH				
			14,300# resin coated sand.			
	3159'-3451'		Acidized w/2000 gals 15% HCl acid. Frac'd w/27,500 gals gel + 70,000# 20/40 Brady Sand + 20,000# resin coated sand.			
	2874'-3114'		Acidized w/2000 gals 15% HCl acid. Frac'd w/32,500 gals gel + 85,000# 20/40 Brady Sand + 24,000# resin coated sand.			