

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):		38. GEOLOGIC MARKERS	
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Rustler	392	590	
Salado	590	1502	
Tansill	1502	1656	
Yates	1656	1962	
Seven Rivers	1962	2586	
Queen	2586	3005	
Grayburg	3005	3290	
San Andres	3290	4240	
		DEPTH	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)
		3587' - 3712'	Acidized w/6000 gals 15% HCl acid. Frac'd w/25,500 gals gel + 73,000# 20/40 Brady sand + 20,000# 16/30 SLC resin coated sand.
		3128' - 3425'	Acidized w/5000 gals 15% HCl acid. Frac'd w/39,000 gals gel + 131,000# 16/30 Brady sand + 24,000# 16/30 SLC resin coated sand.