

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries);				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	394	600				
Salado	600	1456				
Tansill	1456	1616				
Yates	1616	1916				
Seven Rivers	1916	2544	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)			
Queen	2544	2956				
Grayburg	2956	3258				
San Andres	3258	4190 (TD)				
		DEPTH				
			gals gel + 56,000# 20/40 Brady sand + 16,000# resin coated sand.			
	3296'-3431'		Acidized w/900 gals 15% HCl acid.			
	3016'-3236'		Acidized w/1500 gals 15% HCl acid.			
	3016'-3431'		Frac'd w/36,000 gals gel + 119,000# 20/40 Brady sand + 24,000# resin coated sand.			