Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103	C
Revised 1-1-	89

DISTRICT P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

SUNDRY NOTICES AND REPORTS ON WELLS

DISTRICT II SUPERVISOR

APPROVED BY -

P.O. Box 2088 Santa Fe, New Mexico 87504-2088 WELL API NO. 30-015-28487

5. Indicate Type of Lease STATE FEE L

6. State Oil & Gas Lease No. LG-5665

DATE -

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7. Lease Name or Unit Agreement Name				
	ype of Well:	GAS							
W	ÆLL.	WEI	LX	OTHER					G State Com
	lame of Operato							8. Well No.	1
YATES PETROLEUM CORPORATION							9. Pool name or Wildcat		
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210						Cedar Lake Morrow			
		rourth	Street	- Altesia, Nri o				Gedal L	ake Hollow
4. \ 	Well Location Unit Letter	<u> </u>	660	Feet From The Nort	:h	Line and	223	O Feet From	The West Lin
077	Section	36		Township 17S 10. Elevation (Show	Rai whether	nge 30E DF, RKB, RT, GR, etc.		NMPM 1	Eddy County
				////	360	2' GR			<u> </u>
11.	N		_	opropriate Box to Inc NTION TO:	dicate 1	Nature of Notice	e, Ro SUB	eport, or Other SEQUENT R	Data EPORT OF:
PERF	ORM REMED	IAL WORK		PLUG AND ABANDON		REMEDIAL WORK	К		ALTERING CASING
TEM	PORARILY AB	IANDON		CHANGE PLANS		COMMENCE DRI			PLUG AND ABANDONMENT (
PULL	OR ALTER C	ASING	Ц			CASING TEST AN			face casing & cmt
OTH					_ [_]				
1	Resumed 6 542' at casing s 496'. C weight 1 (yield 2 1.33, we circulate Tagged c 1-1/4 ho 1:00 AM with 4% Spotted Tagged c 1-1/4 ho	drilling 3:30 PM 1 et at 54% emented v 3.87) and .00, weig ight 14.8 e. WOC 5 ement at ur. Ran 11-2-95. CaC12. 1 50 sacks ement at ur. Ran	a 17-1 10-31-9 2'. 1- with 10 d 350 s ght 12. 3). PD 5 hours 304'. 1". T WOC 1 PD 2:30 "C" wi 300'. 1". T	00 sacks Thixset, sacks Howco Lite, 45). Tailed in	tary to sof the definition of	tools at 9:00 13-3/8" 54.5# guide shoe s /sack flocele /sack flocele 200 sacks Pre nped plug to rvey and foun with 4% CaCl Spotted 50 Tagged cement /4 hour. Rar AM 11-2-95. with 4% CaCl Spotted 75	0 AM # 8r set e, 5 emium 500 nd t 12. sac t at wo 12. sac	d J-55 ST&C at 542'. In O#/sack gilso m Pluble psilok. Co op of cement PD 11:30 NOW ks "C" with 304' Spot C 4-1/2 hour PD 9:00 AM ks "C" with	Reached TD of (550.45') of sert float set at onite (yield 1.58, nite and 3% CaC12 lield at 304'. Ran 1". 11-51 1955 WOC 4% CaC12. PD to 50 sacks "C" 11-2-95. WOC 4% CaC12.
	GNATURE	Rusty	Klein	lev	Т	me Producti	1011	OTOTA	505-748-1471. TELEPHONE NO.
				ved by Tim W. Gun	1				NOV 2 0 1995