	State of New Mexico		Form C.103 Revised 1-1-89		
to Appropriate District Office	fice			Revised 1-1-67	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL. API NO. 30-015-28487		
DISTRICT II P.O. Drawer DD, Anesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease I	No.	
-			LG-566		
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Ag	reement Name	
1. Type of Well: Oft. WELL WELL X	) ONER		Cedro APG S	tate Com	
2. Name of Operator	,		8. Well No.		
YATES PETROLEUM CORPORATION			9. Pool name or Wildcat		
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210			Cedar Lake Morrow		
4. Well Location	Gedat have horrow				
Unit Letter $\underline{C}$ : <u>66</u>	0 Feet From The North	Line and22	30 Feet From The	West Line	
26	Township 17S	Range 30E	NMPM Edd	y County	
Section 36	Township 175 10. Elevation (Show wh	heiher DF, RKB, RT, GR, etc.) 3602' GR			
Y/////////////////////////////////////					
II. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
NOTICE OF IN	HENTION TO:				
	PLUG AND ABANDON				
	CHANGE PLANS				
PULL OR ALTER CASING			CASING TEST AND CEMENT JOB   OTHER: Perforate, acidize & frac   X		
12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-16-96 - Rigged up wireline. TIH with 4" casing guns and perforated 10853-10858' w/24. .42" holes (Atoka). TOOH with guns and rigged down wireling in the proposed toping down. Digged up set at 10787'. Nippled down BOP and nippled up tree. Swapped toping down. Digged up tree saver and Halliburton equipment. Acidized perforations 10853-10858' with 1000 gallons 7-1/2% Morrow acid with 1000 scf/bbl N2. Nippled down treesaverAN 219w1906 well to pit.					
1 17 06 - Swabbed Shut well in.					
1-23-96 - Rigged up treesaver and Halliburton frac equipment. Tespendinges to 12000 psi. Frac'd perforations 10853-10858' (via 2-7/8" tubing) with 22000 gallons 65 Quality CO2					
and 25000# DC TM sand. Pressured out. Cut sand 002 Frugh with the Indicated tubing had in. Rigged down treesaver. Shut in for 4 hours. Opened to pit. Indicated tubing had bridged off. TIH with 1-1/4" coiled tubing. Washed down at 1/4 BPM to 6000'. Hit sand bridged off. TIH with 1-1/4" coiled tubing. Washed to PBP at 10945'. TOOH w/coiled					
bridge Recovered CO2 and water. Washed down thru peris to KBI at 10949 . Tool wy the					
tubing. Nippled dow	m coiled tubing unit.	Swabbing.			
I hereby certify that the information above in	······································	iedge and belief.		1_26_96	
SIGNATURE LUSLYT	flin	Production	Clerk	DATE 1-26-96	
TYPE OR PRINT NAME RUSTY KIE	in			505-748-1471 TELEPHONE NO.	
(This space for State Use)	IGNED BY TIM W. GUM			FEB -1 1996	
	SUFERVISOR	πιε		DATE I IJJO	

-