

3-11-98:
Attachment
OCD Form C-103
Jenna, Well #1, aPI #30 025 29260

Continued:

1-16-98: RIH w/pkr set @ 6963', rig up swab, seating nipple @ 6956'.
1-19-98: RIH w/swab, RIH to seating nipple, POOH, rigged up reverse unit, loaded tbg
w/1% KCL water, pressured up to 1000#, held, unset pkr & POOH, SION.
1-24/30/98: Swabbed.