

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE \*  
(Other Instructions on  
reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

1512

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-029420-A	
2. NAME OF OPERATOR The Wiser Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241		7. UNIT AGREEMENT NAME Skelly Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2564' FSL & 1415' FEL Sec. 15-T17S-R31E Unit J		8. API WELL NO. 30-015-29312	
		9. WELL NO. 191	
		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7-Rivers	
		11. SEC., T., R., M., OR B.L.K. AND SURVEY OR AREA Sec. 15-T17S-R31E	
14. PERMIT NO	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3876'	12. COUNTY OR PARISH Eddy	13. STATE NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT * <input checked="" type="checkbox"/>

(Other) Perforate & Acidize

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

02/24/97 POH w/2-7/8" tbg. & R/TTS pkr. RIH w/4-3/4" bit & 4 3-1/2" DC's on 2-7/8" tbg. Tagged cmt. @ 3411'. RU reverse unit. Drilled cmt. f/3411'-3506'.

02/25/97 Drilled cmt. f/3506'-3710'. Circ. & tested squeeze to 1000#. Held ok. Drilled on CIBP @ 3720'. POH to 3500'.

02/26/97 Tagged CIBP @ 3720'. Drilled CIBP & pushed to 3755'. Drilled CIBP f/3755'-3761'.

02/27/97 Drilled cmt. f/3761'-3775'. Cleaned out to 3857'. POH w/2-7/8" tbg & LD 4 3-1/2" DC's. RIH w/R/TTS pkr. on 2-7/8" tbg. & set @ 3655'. Released pkr.

02/28/97 Halliburton re-perforated San Andres Three Fingers/Upper Massive f/3746', 47', 55', 56', 57', 86'-90', 93', 94', 95', 99', 3800' & 01' w/1 SPF (16 holes). Acidized perfs. 3746'-3801' w/2400 gals. 15% NE-FE acid & 32 ball sealers. Formation broke @ 2657#. Good ball action. MTP 3271# @ 5.2 bpm. ATP 2201# @ 4.3 bpm. Job communicated w/17 bbls. flush left. Shut down & reversed acid out of hole.

03/03/97 Halliburton perforated Grayburg f/3306', 10'-14', 47', 48', 65', 66', 73', 74', 75', 3437'-40', 96'-99', 3505' & 06' w/1 SPF (23 holes). RIH w/R/TTS pkr. & RBP on 2-7/8" tbg. Set RBP @ 3520' & R/TTS pkr. @ 3210'.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Tunney TITLE Completion Department DATE July 16, 1997

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instruction On Reverse Side