	*	
1		
611 S. Adada	101	

0/5/

	· · · · · · · · · · · · · · · · · · ·		
Do not use this form for pro	Y NOTICES AND REPORTS ON oposals to drill or to deepen or relational control of the control of t	my to written Nrese (o)	LC-060999 6. If Indian, Allottee or Tribe Name
	SUBMIT IN TRIPLICATE	MAR 1 0 1997	7. If Unit or CA, Agreement Designation
4 Location of Well (Footage, Sec., T. R	Mack Energy Corporation P.O. Box 960, Artesia, NM 88211-090		8. Well Name and No. McIntyre B #5 9. API Well No. 2 (15 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -
12 CHECK APPROP	RIATE BOX(s) TO INDICATE NA	ATURE OF NOTICE, REPOR	T, OR OTHER DATA
TYPE OF SUBMISSI	NC	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment No	Reco Plug. Casin Alter	ndonment impletion ging Back ng Repair ring Casing or Amend Casing Program on APD	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give subsurface locations and me	ions (Clearly state all pertirent details, and give pertir	zones pertinent to this work	
	A DDD OVAL	SUBJECT TO	

APPROVAL SUBJECT TO **GENERAL REQUIREMENTS AND** SPECIAL STIPULATIONS **ATTACHED**

4. I hereby ceruffy that the foregoing is true and correct				24407
Signed (Lease) (ale	Title	Production Clerk	Date_	3/5/97
(This space for Federal or State office use) Approved (ORIG. SGD.) ALEXIS C. SWOBODA Conditions of approval, if any:	Title	PETROLEUM ENGINEER	Date _	3/7/97

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CONDITIONS OF APPROVAL - DRILLING

Operator's Name: Mack Energy Corporation Well Name & No. McIntyre B Federal #5

Location: 2183' FSL, 990' FWL, Section 20, T17S R30E, Eddy County, NM

Lease: LC-060999

I. DRILLING OPERATIONS REQUIREMENTS:

The Bureau of Land Management (BLM) is to be notified at the Carlsbad Resource Area Office, 620 East Greene St., Carlsbad, NM 88220, (505) 887-6544 for wells in Eddy County in sufficient time for a representative to witness:

- 1. Spudding
- 2. Cementing casing: 8-5/8 inch 5-1/2 inch
- 3. BOP tests
- 4. A Hydrogen Sulfide (H2S) Drilling Operation Contingency Plan shall be activated prior to drilling into the <u>Queen</u> formation. A copy of the plan shall be posted at the drilling site.
- 5. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- 6. The API No. assigned to the well by NMOCD shall be included on the subsequent report of setting the first casing string.

II. CASING:

- 1. The 8-5/8 inch surface casing shall be set at 450 feet and cement circulated to the surface. If cement does not circulate to the surface the appropriate BLM office shall be notified and a temperature survey or cement bond log shall be run to verify the top of the cement. Remedial cementing shall be completed prior to drilling out that string.
- 2. The minimum required fill of cement behind the 5-1/2 inch production casing is to tie 200 feet into the 8-5/8 inch casing.

III. PRESSURE CONTROL:

Before drilling below the surface casing shoe, the blowout preventer assembly shall consist of a minimum of: One Annular Preventer and/or Two Ram-Type Preventers and a Kelly Cock/Stabbing Valve.

Minimum working pressure of the blowout preventer and related equipment (BOPE) shall be 2000 psi.

The BOPE shall be installed before drilling below the 8-5/8 inch casing and shall be tested as described in Onshore Order No. 2. Any equipment failing to test satisfactorily shall be repaired or replaced.

The appropriate BLM office shall be notified in sufficient time for a representative to witness the tests.

03/05/97 acs