



marbob
energy corporation

September 4, 2002

*Oil Conservation Division
1301 W. Grand Ave.
Artesia, NM 88210*

Attn: Gerry Guye


*Re: Sand Tank 32 State Com #2
J-32-17S-30E
30-015-29513
Inspection Violation*



Gerry:

*In response to your letter of August 20, 2002 (copy attached),
the violation on the above referenced well has been corrected and
the well is ready for re-inspection.*

*If you have any questions or require further information,
please don't hesitate to contact me.*

Sincerely,

*Diana J. Cannon
Production Analyst*

Accepted for record • NMOCD



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor

Betty Rivera

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

Field Inspection Program
"Preserving the Integrity of Our Environment"

AUG 23 2002

20-Aug-02

MARBOB ENERGY CORP

PO BOX 227

ARTESIA NM 88211-0227



Dear Operator:

The following inspection(s) indicate one or more violations as described in the detail section below. The inspection(s) indicates that the well, equipment, location or operational status failed to meet standards of the New Mexico Oil Conservation Division. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section below indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division.

Please notify the proper district office of the Division of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

SAND TANK 32 STATE COM 002

J-32-17S-30E

30-015-29513-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/20/2002	MIT Witnessed - Pre	Gerry Guye	Yes	No	11/23/2002	iGEG0219634739
Comments on Inspection: Unable to witness bradenhead because it is not plumbed to surface.						

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,

Oil Conservation Division, District II

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.