Submit 3 Copies	State of New M	Iexico		alch
to Appropriate	Energy, Minerals and Natural F		Form C-103	(),
District Office		tobe are est bepartment	Revised 1-1-8	9 11
DISTRICT I	OIL CONSERVATIO	N DIVISION		
P.O. Box 1980, Hobbs NM 88240	2040 South Pac		WELL API NO.	<u>`</u> #
DISTRICT II	Santa Fe, New Mex		30-015-30005	4
811 South First, Artesia, NM 88210	Santa Pe, New Mex	100 8/505	5. Indicate Type of Lease	
DISTRICT III				ee 🗖
1000 Rio Brazos Rd, Aztec, NM 87410	6. State Oil & Gas Lease No.			
			V-4381	
SUNDRY NO	TICES AND REPORTS ON W	/FILS		
(DO NOT USE THIS FORM FOR PRO				
DIFFERENT RESI	7. Lease Name or Unit Agreement Name			
(FORM	C-101) FOR SUCH PROPOSALS).	20.25-25-22 Star		
1. Type Of Well:				
OIL GAS WELL	OTHER	T	Juniper State	
2. Name of Operator	<u>(3)</u>	JAN 1998	8. Well No.	
Mack Energy Corporation	에 있는 것이 있는 것이 있는 것이 있다. [1] 전 1	DEOFINED	8. Well No.	
3. Address of Operator		OCD - ARTESIA	9. Pool name or Wildcat	
P.O. Box 960, Artesia, NM 88211-0)960 (et al.	ULD - ARTESIA		
4. Well Location			Loco Hills Paddock	
Unit Letter M : 890	Feet From The South	20	•	
	Feet From The South	Line and 99	0 Feet From The West	Line
Section 16	Township 17S Ra	ange 30E N	мрм Eddy c	
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)		County
		3662		
^{11.} Check A	ppropriate Box to Indicate 1	Nature of Notice, Re	port, or Other Data	
NOTICE OF INT	ENTION TO:		SEQUENT REPORT OF:	
	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONM	
PULL OR ALTER CASING				
		CASING TEST AND CEN	NENT JOB	
OTHER:		OTHER T	D, Cement Long String Csg	\bowtie
		1		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/20/98 TD 7 7/8" hole @ 12:00 a.m. @ 4770' Rig Schlumberger and log well.

1/21/98 Ran 107 joints 5 1/2" 17# LT&C J-55 New Casing, Landed 5 1/2" casing @ 4754.42', DV tool @ 4076', marker jt @ 3930'. BJ Service Cemented 1st stage w/160 sacks 50/50 Poz with 2%gel, 5/10% HL25, 5# salt, open DV tool, circ 57 sacks, plug down at 6:30 a.m. wait 6 hrs, Cemented 2nd stage w/ 850 sacks BJ Lite 35/65 6% gel, 3# salt, 1/4# celoflake, tail in with 350 sacks of 50/50 POZ C with 6% gel, 5/10% HL25, 6# salt circ 60sx, plug down at 2:30 p.m. WOC 12 hrs, tstd csg to 600# for 20 minutes - held okay.

	uginal giover py tim W. Gu Strict II Supenvisor	M		JAN 27 1998	
TYPE OR PRINT NAME	Crissa D. Carter			TELEPHONE NO. 748-1288	
SIGNATURE	ussa D. Carter	TITLE	Production Clerk	DATE 1/22/98	

CONDITIONS OF APPROVAL, IF ANY: