

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

3001530799

5. Indicate Type of Lease

STATE ☒

FEE

6. State Oil / Gas Lease No.

7. Lease Name or Unit Agreement Name

TEXMACK 2 STATECOMM

8. Well No.

2

9. Pool Name or Wildcat

FREN MORROW

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator

205 E. Bender, HOBBS, NM 88240

4. Well Location

Unit Letter F : 1980 Feet From The NORTH Line and 2180 Feet From The WEST Line

Section 2 Township 17-S Range 31-E NMPM EDDY COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☒

Completion ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-20/3-9/00: PU BIT, DC'S & TBG & TIH. TAG CMT @ 8595./ DRLG 8595-8694, 8799. TAG CMT W/TBG @ 12097. DRLG 12097-12454. DISPL W/MORROW WATER & SPOT 100 GALS 10% ACETIC FR 12225-12125. RUN GR/CNL FR 11960-11000. CORRELATE W/PLATFORM EXPRESS @ 12144-12160, 12180-12188. NDBOP. NU TREE. FLOWED BACK 15 BBL WATER. TEST LINES TO 9000 PSI. L ACIDIZE W/2500 GALS M7 1/2% GAS WELL ACID W/1670 HAL METHANOL. PUT WELL THRU TEST SEP & METER RUN W/40# BACK PRESS. TIH W/TANDEM BOMBS SET BOMBS IN ON/OFF TOOL @ 11947. TIH & RETRIEVE BOMBS. TIH W/GUN RELEASE TOOL. TIH W/PLUG SET @ 11964. MIRU COMPLETION UNIT. NU BOP & TEST TO 1500 PSI. TIH W/3 1/2" FRAC STRING. RAN IN 375 JTS. NDBOP. NU FRAC TREE. TEST ANNULUS TO 3000 PSI-OK. OPEN WELL & FLOW DN. FRAC MORROW W/70% QUALITY CO2, 25% METHANOL, 43000# 20/40 BAUXITE. TURNED FLOW THRU SEPR. TIH W/PLUG SAT DOWN ON TOP OF ON/OFF TOOL. TIH W/OVERSHOT & RETR PLUG. RU COIL TBG UNIT. WASH OUT SAND FR NIPPL3ES W/FOAMED KCL WATER. RD. TIH W/PLUG & SET @ 11964. ND TREE & NUBOP. PU ON/OFF TOOL & TIH. SPACE OUT & LATCH ONTO PKR. NDBOP. NU TREE. RU SWAB EQPT. SWAB DN TO 5900'. TIH W/SHORT CATCH OVERSHOT. DID NOT LATCH. TIH W/BAILER. FLOW WELL TO TRY & CLN PLUG. SHEARED OFF PLUG. JET CUT PKR TP @ 11964. WELL FLOWING.

3/21/00: ON 24 HR OPT. FLOWING 34 BO, 600 MCF, 0 BW.
FINAL REPORT



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. Denise Leake

TITLE Engineering Assistant

DATE 4/18/00

TYPE OR PRINT NAME

J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY:

TITLE

**ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR**

DATE

4-28-00