

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

95.7
Form C-103
Revised March 25, 1999

| | | |
|---|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | WELL API NO. 30-015-30920 |
| 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> | | 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 2. Name of Operator Clayton Williams Energy, Inc. | | 6. State Oil & Gas Lease No. B6846 |
| 3. Address of Operator Six Desta Drive, Suite 3000, Midland, Texas 79705 | | 7. Lease Name or Unit Agreement Name: STATE '20B' |
| 4. Well Location Unit Letter <u>A</u> : <u>430</u> feet from the <u>north</u> line and <u>990</u> feet from the <u>east</u> line Section <u>20</u> Township <u>17S</u> Range <u>29E</u> NMPM <u>Eddy</u> County | | 8. Well No. 3 |
| 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3613' | | 9. Pool name or Wildcat (28509) Grayburg Jackson-7R's, QN, GB, SA |

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

July 18 thru **31**, 2000

- Set RBP @ 3800' and temporarily abandon Yeso perms.
- Perforate Lower San Andres 3540'-3762', 20 shots. Stimulate Lower San Andres.
- Set RBP @ 3200'.
- Perforate Upper San Andres 2474'-3045', 24 shots. Stimulate Upper San Andres.
- Set RBP @ 2420'.
- Perforate Grayburg Jackson 1951' - 2388', 26 shots. Stimulate Grayburg Jackson.
- Retrieve RBP's at 3200' and 2420'. Clean out to BP at 3800'.
- Run tubing, rods and pump.
- Start pumping load water.

RECEIVED
OCD ARTS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Betsy Luna TITLE Engineering Technician DATE 8/21/00
Type or print name Betsy Luna Telephone No. (915) 682-6324

(This space for State use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR BX

APPROVED BY BX TITLE DATE AUG 28 2000
Conditions of approval, if any:

