Submit 3 Copies To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 South First, Artesia, NM 88210State of New Mexico Energy, Minerals and Natural ResourcesForm C-103 Revised March 25, 1999OIL CONSERVATION DIVISION District III 2040 South PachecoOIL CONSERVATION DIVISION 5. Indicate Type of Lease
Office   Energy, Minerals and Natural Resources     District I   Energy, Minerals and Natural Resources     1625 N. French Dr., Hobbs, NM 88240   WELL API NO.     District II   OIL CONSERVATION DIVISION     811 South First, Artesia, NM 88210   OIL CONSERVATION DIVISION
I625 N. French Dr., Hobbs, NM 88240     WELL API NO.     District II     OIL CONSERVATION DIVISION     Substrict II     811 South First, Artesia, NM 88210     OIL CONSERVATION DIVISION     Substrict II
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION 5. Indicate Type of Lease
5 Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505
2040 South Pacheco, Santa Fe, NM 87505
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN ØR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C tol) FOR SUCH
1. Type of Well:
Oil Well Gas Well Other   2. Name of Operator Image: Construction of the second s
2. Name of Operator Clayton Williams Energy, Inc.
3. Address of Operator 8. Pool name or Wildcat
Six Desta Drive, Suite 3000, Midland, Texas 79705 Empire, East (Yeso) 96610
4. Well Location
Unit Letter <u>O: 330</u> feet from the <u>south</u> line and <u>2310</u> feet from the east line
Unit Letter O: 330 feet from the <u>south</u> line and <u>2310</u> feet from the <u>east</u> line
Section 20 Township 17S Range 29E NMPM Eddy County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3612' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
11. Check Appropriate box to indicate nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDON   Image: Completion
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD   PLUG AND ABANDONMENT
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD   Image: SPUD     12. Describe proposed or completed operations.   (Clearly state all pertinent details, and give pertinent dates, including estimated date.
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD   PLUG AND ABANDONMENT
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD   Image: Sput State all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   OTHER:   TEMPORAGE operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD   Image: Sput State all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD     12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.     3/6/00:   Spud 12-1/4" hole at 1:00 p.m. 3/6/2000. Drilling Contractor: Norton Drilling Company, Rig #15'.     3/7/00:   Drill 12-1/4" hole to 467'. Run and set 10 jts. of 8-5/8" 24# K-55 ST&C casing, set at 465'. Cement with 300 sx.
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPULD   Image: Spul 12-1/4" hole at 1:00 p.m. 3/6/2000. Drilling Contractor: Norton Drilling Company, Rig #15'.
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD     12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.     3/6/00:   Spud 12-1/4" hole at 1:00 p.m. 3/6/2000. Drilling Contractor: Norton Drilling Company, Rig #15'.     3/7/00:   Drill 12-1/4" hole to 467'. Run and set 10 jts. of 8-5/8" 24# K-55 ST&C casing, set at 465'. Cement with 300 sx.
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD     12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.     3/6/00:   Spud 12-1/4" hole at 1:00 p.m. 3/6/2000. Drilling Contractor: Norton Drilling Company, Rig #15'.     3/7/00:   Drill 12-1/4" hole to 467'. Run and set 10 jts. of 8-5/8" 24# K-55 ST&C casing, set at 465'. Cement with 300 sx.
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD     12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.     3/6/00:   Spud 12-1/4" hole at 1:00 p.m. 3/6/2000. Drilling Contractor: Norton Drilling Company, Rig #15'.     3/7/00:   Drill 12-1/4" hole to 467'. Run and set 10 jts. of 8-5/8" 24# K-55 ST&C casing, set at 465'. Cement with 300 sx.
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD     12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.     3/6/00:   Spud 12-1/4" hole at 1:00 p.m. 3/6/2000. Drilling Contractor: Norton Drilling Company, Rig #15'.     3/7/00:   Drill 12-1/4" hole to 467'. Run and set 10 jts. of 8-5/8" 24# K-55 ST&C casing, set at 465'. Cement with 300 sx.
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON     PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB   PLUG AND ABANDONMENT     OTHER:   OTHER:   OTHER:   OTHER:   SPUD     12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.     3/6/00:   Spud 12-1/4" hole at 1:00 p.m. 3/6/2000. Drilling Contractor: Norton Drilling Company, Rig #15'.     3/7/00:   Drill 12-1/4" hole to 467'. Run and set 10 jts. of 8-5/8" 24# K-55 ST&C casing, set at 465'. Cement with 300 sx.

ephone No. (915) 682-6324	
DATE_3 -/3	-cc
-	