5

MINIMUM BLOWOUT PREVENTER REQUIRE. 2000# BOP system utilized 3000# WP BOP Equipment 2000# psig WP casing head

STACK REQUIREMENTS

| No. | tem | | Min. 1.D. | Min. Nominal |
|------------|--|------------------|--------------|-----------------|
| 1 | Flowline | | | |
| 2 | Fill up ine | | | 2- |
| 3 | Orilling napple | | • • | |
| 4 | Annular preventer | | | |
| 5 | Two single or one dual hy operated rams | | | |
| 64 | Orilling spool with 2" min. 3" min choke line outlets | 0f | | |
| 6 b | 2" min. kill line and 3" min. choke line outlets in ram. (Atternate to 6a above.) | | | |
| 7 | Valve | Gate 🗆 Piug 🗆 | 3-1/8* | |
| 8 | Gate valve-power operated | | 3-1/8" | |
| 9 | Line to choke manifold | | | 3- |
| 10 | Valves | Gete 🖸 Plug 🗖 | 2-1/16" | |
| 11 | Check valve | | 2-1/16* | |
| 12 | Casing head | | | |
| 13 | Valve | Gate 🗆 Plug 🗆 | 1-13/16* | |
| 14 | Pressure gauge with needle valve | | | |
| 15 | Kill line to rig mud pump manifold | | | 2* |

| OPTIONAL | | | | | | | | |
|----------|---------------|--|----------|--|--|--|--|--|
| 16 | Flanged valve | | 1-13/16* | | | | | |
| | | | | | | | | |

CONTRACTOR'S OPTION TO FURNISH:

- 1.All equipment and connections above bradenhead or casinghead. Working pressure of preventers to be 3,000 psi, minimum.
- Automatic accumulator (80 gallon, minimum) capable of cirsing BOP in 30 seconds or less and, holding them closed against full rated working pressure.
 BOP controls, to be located near drillers
- position.
- 4.Kelly equipped with Kelly cock.
- S.Inside blowout prevventer or its equivalent on derrick floor at all times with proper threads to fit pipe being used.
- 6.Kelly saver-sub equipped with rubber casing protector at all times.
- 7.Plug type blowout preventer tester. 8.Extra set pipe rams to fit drill pipe in use on location at all times.
- S. Type RX ring gaskets in place of Type R.

MEC TO FURNISH:

- 1.Bradenhead or casinghead and side valves.
- 2.Wear bushing, if required.

GENERAL NOTES:

- 1. Deviations from this drawing may be made only with the express permission of MEC's Orifling Manager.
- 2.All connections, valves, fittings, piping, etc., subject to well or pump pressure must be flanged (suitable clamp connections acceptable) and have minimum³ working pressure equal to rated working pressure of preventers up through chore. Valves must be full opening and suitable for high pressure mud service.
- Controls to be of standard design and each marked, showing opening and closing position.
- 4. Chokes will be positioned so as not to hamper or delay changing of choke beans. Repleceable parts for adjustable choke, other bean sizes, retainers, and choke wrenches to be conveniently tocated for immediate use.
- S.All valves to be equipped with hand- . wheels or handles ready for immediate use.
- \$.Choke lines must be suitably anchored.

EXHIBIT #1



- 7.Handwheels and extensions to be connected and ready for use.
- Valves adjacent to drilling spool to be kept open. Use outside valves except for emergency.
- All seamless steel control piping (3000 psi working pressure) to have flexible joints to avoid stress. Hoses will be permitted.
- 10.Casinghead connections shall not be used except in case of emergency.
- 11.Do not use kill line for routine fill-up operations.