

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	MEAS. DEPTH	TOP TRUE VERT. DEPTH
				Rustler	366'	
				Salado	512'	
				Tansill	1328'	
				Yates	1488'	
				Seven Rivers	1796'	
				Bowers	2188'	
				Artesia (Queen)	2422'	
				Penrose	2592'	
				Grayburg	2788'	
				San Andres	3108'	
			DEPTH			
			ACID, SHOT, FRACTURE, CEMEMNT SQUEEZE, ETC.. (continued from the front)			