# MINIMUM BLOWOUT PREVENTER REQUIREMEN. 2000# BOP system utilized 3000# WP BOP Equipment 2000# psig WP casing head

### STACK REQUIREMENTS

No.	tem		Min. 1.D.	Min. Nominal
1	Flowine			
2	Fill up line			2*
3	Dniling mpple			
4	Annular prevenier			
5	Two single or one dual hydraulically operated rams			
64	Drilling spool with 2" min. kill line and 3" min choke line outlets			
6b	2" min. kill line and 3" min. choke line outlets in ram. (Alternate to 6a above.)			
7	Vaha	Ne () Ng ()	3-1/8*	
	Gate valve-power operated		3-1/8*	
9	Line to choke manifold			3-
10	G	ug C	2-1/16*	
11	Check valve		2-1/16	
12	Casing head			
13	Mah.a	iii () Iig ()	1-13/16*	
14	Pressure gauge with needle valve			
15	Kill line to rig mud pump manifold			2*

EXHIBIT #1



OPTIONAL						
16	Flanged valve		1-13/16*	l		
<u> </u>						

## CONTRACTOR'S OPTION TO FURNESH:

- All equipment and connections above bradenhead or casinghead. Working pressure of preventers to be 3,000 psi, minimum.
- Automatic accumulator (80 gallon, minimum) capable of cirsing BOP in 30 seconds or less and, holding there closed against full rated working pressure.
- 3.BOP controls, to be located near drillers position.
- 4.Kelly equipped with Kelly cock.
- S.Inside blowout prevventer or its equivalent on derrick floor at all times with proper threads to fit pipe being used.
- 6.Kelly saver-sub equipped with rubber casing protector at all times.
- 7.Plug type blowout preventer tester.
- Extra set pipe rams to fit drill pipe in use on location at all times.
- 9. Type RX ring gaskets in place of Type R.

#### MEC TO FURNISH:

- 1.Bradenhead or casinghead and side valves.
- 2. Wear bushing, if required.

### GENERAL NO 3:

- 1. Deviations from this drawing may be anade only with the express permission of MEC's Dritting Manager.
- 2.All connections, velves, Ittings, piping, etc., subject to well or pump pressure must be flanged (suitable clamp connections acceptable) and have minimum<sup>2</sup> working pressure equal to rated working pressure of preventers up through cho<sup>-1</sup>e. Valves must be full opening and suitable for high pressure and service.
- Controls to be of standard design and each marked, showing opening and closing position.
- 4. Chokes will be positioned so as not to hemper or delay changing of choke beens. Replaceable perts for adjustable choke, other been sizes, retainers, and choke wrenches to be conveniently located for immediate use.
- S.All valves to be equipped with hand-... wheels or handles ready for immediate use.
- 6. Choke lines must be suitably anchored.

- 7. Handwheels and extensions to be connected and ready for use.
- Valves adjacent to drilling spool to be kept open. Use outside valves except for emergency.
- All seemiess steel control piping (3000 psi working pressure) to have flexible joints to avoid stress. Hones will be permitted.
- 18. Casinghead connections shall not be used except in case of emergency.
- 11.Do not use kill line for routine III-up operations.