	ask,
Submit 3 Copies to Appropriate State of New Mexico	Form C-103
Submit 3 Copies to Appropriate District Office DISTRICT I 1625 n. French Dr., Hobbs, NM 88240 DISTRICT II 811 South First, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 DISTRICT IV 2040 S. Pacheco, Santa Fe, NM 87505 SLINDRY NOTICES AND REPORTS ON MACELL BECEINFD	Revised March 25, 1999 WELL API NO.
1625 n. French Dr., Hobbs, NM 88240	WELL API NO.
OIL CONSERVATION DIVISION 13 14 15 7	30-015-31185
811 South First, Artesia, NM 88210 DISTRICT III 2040 South Pacheco	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87305	6. State Oil & Gas Lease No.
DISTRICT IV	0. 0.0.0 0.1 0 000 2000 110.
2040 S. Pacheco, Santa Fe, NM 87505	647, B-949, B-11593
SUNDRY NOTICES AND REPORTS ON WELLS OR RESIDENCE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR DUBE BACK TO A	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	Geronimo "36" State Com
1. Type of Well:	
Oil Well Gas Well X Other	
	8. Well No.
Louis Dreyfus Natural Gas Corp.	1
· · · · · · · · · · · · · · · · · · ·	Pool name or Wildcat
14000 Quail Springs Parkway - Suite 600 - Oklahoma City, OK 73134	Empire South (Morrow)
4. Well Location	
Unit letter C 1060' feet from the North line and 1980' feet fr	om the West line.
Section 36 Township 17S Range 28E N	
Section 36 Township 17S Range 28E N	MPM Eddy County
10. Elevation (Show whether DR, RKB, RT, Gr, etc.) 3680'	
3000	
	。 第一章
11. Check Appropriate Box to Indicate Nature of Notice, Report	t or Other Data
NOTICE OF INTENTION TO: SUBSEQUE	ENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.	PLUG AND
BUIL OF ALTER CASING	ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JO COMPLETION	ов [
OTHER: OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any pro-
propsed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	on or recompletion.
6/23/01 Perf'd Morrow from 10,567 - 10,574, 10,661 - 10,668, 10,672 - 10,674, 10,695 -	10 698 4 spf 6/24/01 acid
job, pumped a total of 2000 gal 15% NeFe acid w/10% methanol & clay control agent, co	
& 60 ball sealers.	•
6/28/01 Set CIBP @ 10,520, dump bail 35' of cement on top. Perf'd upper Morrow f/10,4	137' - 10,442'. 6/29/01, acid
job, pumped a total of 750 gal 15% NeFe acid w/10% methanol and clay control agent.	
6/30/01 Set CIBP @ 10,390', dump bail 35' of cement on top. Perf'd Atoka f/10,252 - 10,	266 4 SPF. Acidizing &
Testing.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE () SI	DATE 07/10/01
SIGNATURE Wegulatory Technician	DATE 07/10/01
Type or print name Carla Christian	Telephone No. 405-749-5263
(This space for State use)	
ORIGINAL SIGNED BY TIM W. GUM	12 200 La 200
APPROVED BY DISTRICT II SUPERVISORE	DATE
Conditions of approval, if any:	