

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
				Rustler Salado Tansill Yates Seven Rivers Bowers Artesia(Queen) Penrose Grayburg San Andres	380' 555' 1482' 1622' 1926' 2297' 2534' 2797' 2960' 3264'	
			ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)			
		DEPTH 3105'- 3461'	Frac'd w/47,160 gals X-Linked gel + 160,800# sand			