

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type Of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	WELL API NO. 30-015-31279
2. Name of Operator Mack Energy Corporation	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960	6. State Oil & Gas Lease No. E-4201
4. Well Location Unit Letter <u>J</u> : <u>2310</u> Feet From The <u>South</u> Line and <u>2185</u> Feet From The <u>East</u> Line Section <u>19</u> Township <u>17S</u> Range <u>29E</u> NMPM <u>Eddy</u> County	7. Lease Name or Unit Agreement Name State S-19
10. Elevation (Show whether DF, RKB, RT, GR, etc) 3680	8. Well No. 16
	9. Pool name or Wildcat Empire Yeso

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER <input checked="" type="checkbox"/> Completion

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/20/2000 Drill out DV tool.,

10/22/2000 Perforate 81 holes at 3828,30.5,45.5,65,72.5,75.5,90,92.5,95.5, 3901.5,03,10,12.5,15,18.5,23,25,30,32,34,50.5,52,53.5,68,71.5,76,78,79.5,83.5,85,90,95, 4001.5,03,09,26,27.5,34,37.5,39.5,41,45,51.5,53, 58.5,65.5, 67, 70.5,72.5,74,75.5,77,81,83,84.5,86,88.5,90,92,94.5,96, 4100.5,04,07.5,10.5,13,18,20,22.5,25,29.5,31.5,34,41, 4276,78,82,83.5, 4331,37,42.

10/23/2000 Acidized perms w/2000 gals 15% NE Acid 3828-4342' 81-holes.

10/24/2000 Reacidized perms w/32,000 gals 20% Acid, 54,000 gal 40# gel, 5000 gals 15% Acid, 4500 gals fresh water.

10/24/2000 RIH w/139 joints 2 7/8" J-55 EUE 8rd, RIH w/2 1/2 x 2 x 20' Brass Nicarb PAP pump, set Lufkin 228 unit, put to pumping. clean up rig down.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Crissa D. Carter TITLE Production Analyst DATE 12/15/00
TYPE OR PRINT NAME Crissa D. Carter TELEPHONE NO. (505)748-1288

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 20 2000

10/10/10

10/10/10