

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88240

**DISTRICT II**  
811 South First, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd, Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
2040 South Pacheco  
Santa Fe, New Mexico 87505

WELL API NO.  
30-015-31507

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
E-4201

7. Lease Name or Unit Agreement Name  
Continental A State

8. Well No.  
7

9. Pool name or Wildcat  
Empire Yeso

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3643 GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS).  
RECEIVED  
OCD - ARTESIA

1. Type Of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Mack Energy Corporation

3. Address of Operator  
P.O. Box 960 Artesia, N. M. 88211-0960

4. Well Location  
Unit Letter F : 2314 Feet From The North Line and 1968 Feet From The West Line  
Section 30 Township 17S Range 29E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Completion <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

01/09/2001 Drill out DV Tool.  
01/10/2001 RU Schlumberger log & perforate 3903'-4239' 92 holes.  
01/11/2001 Acidize w/2500 gals 15% NEFE acid.  
01/12/2001 Reacidized w/32,000 gals 20% HCL & 54,000 gals 40# gel, 5000 gals 15% HCL Flush w/90 bbls FW.  
01/13/2001 RIH w/141 joints 2 7/8" J-55 tubing. SN landed @ 4270'. RIH w/2 1/2x2x16' RHBC HVR PAP BNC pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tim W. Gum TITLE Production Analyst DATE 2/9/01

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

**ORIGINAL SIGNED BY TIM W. GUM**  
**DISTRICT II SUPERVISOR**  
*AG*

**FEB 13 2001**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: