



- ⊙ Wind Direction Indicators (wind sock or streamers)
- △ H2S Monitors (alarms at bell nipple and shale shaker)
- Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"
RIG LAYOUT PLAT

HUDSON OIL COMPANY OF TEXAS.
WARHOL # 1
UNIT "G" SECTION 13
T17S-R31E EDDY CO. NM