

[illegible]

Det	4221-81	1'	rec 50' sub w
	fp. 34-45	20" si failed	
SP Det	4222-4230	1'	rec 200' sub
	W	fp 55-56	
	30" si	1' 10"	
	TL 5150 li	TLT	3617-3710
C	5210-5330	rec 50'	drill NS
C	5537-5605	rec 49'	drill 550
	Probe Packer Tests (straddle Packers)		
	5546-94	rec 31 O & W + 2 B sub w	6'
	4712-27	rec 18 K & W + 17 B	
	sub w	5'	
	Correct GPR - 1000 ft, 716, 720		
	TL 5750 li	Prof drill	
(SP) Det	3680-3710	A 500 T/H +	
	sub w	4 R & W + 5 B sub w	4'
	J 6425 dr 57 li		
Det	5860-5910	1' 50"	rec 5840'
	sub w	fp 320-2585	30" si 2665"
	J 7420 li	rec 100' sub	
	J 8220 li	1st	
	J 8220 li	1st	
	TL 1200 li	sub	
	1st		
Det	8170-9060	1'	g 55" rec
	147' m	fp 10	30" si 715"
Det	7000-7100	1'	sub
Det	1000-1100	2'	rec 210 m
	1000-1100		