NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

tional instructions	m the Nuts and			e of Notice by Ch	ecking Below			
Notice of Intent to Change Plans			Notice of Intel Temporarily A			ice of Intention PRILL DEEPER	I	
Notice of Intent to Plug Well	rion	X	Notice of Inter to Plug Back	NTION		ice of Intention et Liner	•	
Notice of Intent to Squeeze	rion		Notice of Inte	NTION		ice of Intention hoot (Nitro)	ī	
Notice of Intent to Gun Perforat			Notice of Inter (Other)	NTION		ice of Intention her)		
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO			Midland,	Midland, Texas		8 -2 7 - 56		
Gentlemen:				(Place)		•	(Date)	
Following is a Notice of Intention to do certain work as describe Frank B. Waters (Company or Operator) SW NW 10 10 18S (10-acre Subdivision)								
CT. I	(Company o	r Operator)		Lease	Well	No	in	(Unit)
(40-acre Subd Eddy		10	, T185	, R. 26E	,NMPM.,	C&.	•••••••	Poo
		Cou	nty.					
Pmna		OLLOW	INSTRUCTIONS		ES AND REGUL	ATIONS)		
Propo	se to plug 1125' - 960' -	and ab 12001		Propose to 23 sacks 9 sacks	ES AND REGUL	ATIONS)	s as foll	Lows :
Propo	se to plug	and ab 1200' 985'	INSTRUCTIONS	Propose to 23 sacks	ES AND REGUL	ATIONS)	s as foll	Lows :
	1125' - 960' - 650' - Surfac	and ab 1200' 985' 700'	INSTRUCTIONS	Propose to 23 sacks 9 sacks 16 sacks 2 sacks	es and regul	ATIONS)	s as fol	Lows:
Propo	se to plug 1125' - 960' - 650' - Surfac se to leave	and ab 1200' 985' 700' e all o	INSTRUCTIONS andon well.	Propose to 23 sacks 9 sacks 16 sacks 2 sacks sing in hole	spot total Frank	ATIONS)	s as fol	Lows:
Propo	se to plug 1125' - 960' - 650' - Surfac se to leave	and ab 1200' 985' 700' e all o	instructions and well.	Propose to 23 sacks 9 sacks 16 sacks 2 sacks sing in hole	Frank Produce	of 50 sack of 50 sack Waters		Lows:
Propo	1125' - 960' - 650' - Surfac se to leave	and ab 1200' 985' 700' e all o	instructions andon well. f 8 5/8" cas	Propose to 23 sacks 9 sacks 16 sacks 2 sacks sing in hole	Frank Produce	of 50 sack	eer	Lows:
Propo Approved Except as follows:	1125' - 960' - 650' - Surfac	and ab 1200' 985' 700' e all o	instructions andon well. f 8 5/8" cas	Propose to 23 sacks 9 sacks 16 sacks 2 sacks sing in hole By	Frank Produce	of 50 sack 3. Waters mpm) or Operator ation Enginenications regarding	eer	Lows:
Propo Approved Except as follows:	1125' - 960' - 650' - Surfac se to leave	and ab 1200' 985' 700' e all o	instructions andon well. f 8 5/8" cas	Propose to 23 sacks 9 sacks 16 sacks 2 sacks sing in hole By	Frank I Produce Send Commu	of 50 sack 3. Waters ation Enginentiations regardings	eer	Lows: