

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO JUN 25 1982Form C-103
Revised 10-1-78O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease State ☐ Fee ☒
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Atoka Grayburg Unit
9. Well No. 102
10. Field and Pool, or Wildcat Atoka Grayburg
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CELEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- Injection

Name of Operator
Gulf Oil Corporation ✓

Address of Operator
P. O. Box 670, Hobbs, NM 88240

Location of Well
UNIT LETTER A, 990 FEET FROM THE North LINE AND 330 FEET FROM
THE East LINE, SECTION 14 TOWNSHIP 18S RANGE 26E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
3302' GL16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Tag CIBP at 869'. Circulate hole with abandonment mud. Spot 35' plug on CIBP.
Spot 123' surface plug. Set dry hole marker. Clean location. P&A 5-27-82.

Posted ID-2
6-11-82
P & A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. Pitzer TITLE Area Engineer DATE 5-28-82

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: