

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
300-150-02110051

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Hondo LFE

1. Type of Well:  
OIL WELL ☐ GAS WELL ☒ OTHER

8. Well No.

1

2. Name of Operator  
MWJ Producing Company

9. Pool name or Wildcat  
Atoka Penn

3. Address of Operator  
400 W. Illinois, Ste. 1100, Midland, TX 79701

4. Well Location  
Unit Letter P : 990 Feet From The South Line and 990 Feet From The East Line

Section 19

Township 18S

Range 26E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3442' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing Record: 8-5/8" @ 1289' - TOC @ Surf, 4-1/2" @ 9124' TOC @ 8200'

Perforations: 8992-9020' & 9056-9069'

Proposed Plugging Procedure:

1) Set 50 sx @ 9070-8940' & Tag

2) Set 50 sx @ 8670-8540'

3) Set 25 sx @ 8250'

4) Set 25 sx @ 7250', Perf & Squeeze

5) Set 25 sx @ 6842', Perf & Squeeze

6) Set 35 sx @ 5600'

7) Set 35 sx @ 4350'

8) Set 35 sx @ 2300'

9) Set 35 sx @ 1250' & tag

10) Set 35 sx @ 350'

11) Set 10 sx @ surf & install dry-hole marker

Notify N.M.O.C.C. in sufficient time to witness

*Plugging*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Sabra Fury*

TITLE

Agent

DATE

6/10/92

915/

TELEPHONE NO.

682-5216

TYPE OR PRINT NAME

Sabra Fury

(This space for State Use)

APPROVED BY

*Ed Lillian*

TITLE

*Bill Ry*

DATE

7/2/92

CONDITIONS OF APPROVAL, IF ANY: