	Ene. Minerals and Natural I	lexico Resources Department	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATI P.O. Box 20	)88	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III		5. Indicate Type of Lease STATE FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & Gas Lease No.	
( DO NOT USE THIS FORM FO	NOTICES AND REPORTS ON WE	N OR PLUG BACK TO A	2. Lease Name or Unit Agreement Name
	RESERVOIR. USE "APPLICATION FOR P DRM C-101) FOR SUCH PROPOSALS.)	SECEIVE	D
Type of Well: OL	L OTHER SWD	111 1996	Dayton Townsite Com (SWD) 8. Well No.
YATES PETROLEUM CO 3. Address of Operator	RPORATION		-
	Artesia, NM 88210	DIL CON. D	Dayton
	1650 Feet From The North	Line and231	.0 Feet From The East Line
Section 21			NMPM Eddy County
	10. Elevation (Show whethe	r DF, RKB, KI, GR, etc.)	
	eck Appropriate Box to Indicate		•
]			
PERFORM REMEDIAL WORK		REMEDIAL WORK	
EMPORARILY ABANDON		COMMENCE DRILLING	
PULL OR ALTER CASING		CASING TEST AND CE	
			_
DTHER:	Operations (Clearly state all pertinent details.	OTHER: Acidize i	njection perforations X
12. Describe Proposed or Completed work) SEE RULE 1103. 6-26-96 - Moved in Unset packer. TOO 6-27-96 - TIH with tubing and bailer. gallons of xylene 6-28-96 - Acidized acid and ball seal packer and dropped string. 6-29-7-1-96 - TIH BOP and nippled up Tested annulus to Released well to p	OH and lay down 8800' of on bailer and 2-7/8" tubing TIH with packer and 2-7 down 2-7/8" tubing. Shut d perforations 8902-9062' lers. Flushed and overflu d down thru perfs to knock with nickel plated packer o wellhead. Loaded annulu 600 psi for 30 minutes. production.	OTHER: Acidize i and give pertinent dates, include off. Nippled dow corroded 2-7/8" p g to 9103'. Cais 7/8" tubing. Set well in to soak with 15000 gallo ished with 20000 c balls off. TOO c and 2-7/8" plas is with packer fl Notified OCD-Art	njection perforations X ing estimated date of starting any proposed on wellhead and installed BOP. lastic coated tubing. ng had no fill. TOOH with packer at 8801'. Pumped 500 overnight. overnight. ns gelled 15% iron control gallons fresh water. Unset H and lay down 2-7/8" work- tic coated tubing. Removed uid and set packer at 8822'. esia, but did not witness.
12. Describe Proposed or Completed work) SEE RULE 1103. 6-26-96 - Moved in Unset packer. TOO 6-27-96 - TIH with tubing and bailer. gallons of xylene 6-28-96 - Acidized acid and ball seal packer and dropped string. 6-29-7-1-96 - TIH BOP and nippled up Tested annulus to Released well to p Ihereby certify that the information abov SHONATURE Ruster K	and rigged up pulling up OH and lay down 8800' of a bailer and 2-7/8" tubing TIH with packer and 2-7 down 2-7/8" tubing. Shut l perforations 8902-9062' lers. Flushed and overflu d down thru perfs to knock with nickel plated packer o wellhead. Loaded annulu 600 psi for 30 minutes. production.	OTHER: Acidize i and give pertinent dates, include off. Nippled dow corroded 2-7/8" p g to 9103'. Cais 7/8" tubing. Set well in to soak with 15000 gallo ished with 20000 c balls off. TOO c and 2-7/8" plas is with packer fl Notified OCD-Art	njection perforations X ing estimated date of starting any proposed In wellhead and installed BOP. lastic coated tubing. ng had no fill. TOOH with packer at 8801'. Pumped 500 overnight. ns gelled 15% iron control gallons fresh water. Unset H and lay down 2-7/8" work- tic coated tubing. Removed uid and set packer at 8822'. esia, but did not witness. echnician DATE July 8, 1996
12. Describe Proposed or Completed work) SEE RULE 1103. 6-26-96 - Moved in Unset packer. TOO 6-27-96 - TIH with tubing and bailer. gallons of xylene 6-28-96 - Acidized acid and ball seal packer and dropped string. 6-29-7-1-96 - TIH BOP and nippled up Tested annulus to Released well to p Ihereby certify that the information abov SHONATURE TYPE OR PRINT NAME Rusty K	and rigged up pulling up OH and lay down 8800' of a bailer and 2-7/8" tubing TIH with packer and 2-7 down 2-7/8" tubing. Shut l perforations 8902-9062' lers. Flushed and overflu d down thru perfs to knock with nickel plated packer o wellhead. Loaded annulu 600 psi for 30 minutes. production.	OTHER: Acidize i and give pertinent dates, include off. Nippled dow corroded 2-7/8" p g to 9103'. Cais 7/8" tubing. Set well in to soak with 15000 gallo ished with 20000 c balls off. TOO c and 2-7/8" plas is with packer fl Notified OCD-Art	njection perforations X ing estimated date of starting any proposed on wellhead and installed BOP. lastic coated tubing. ng had no fill. TOOH with packer at 8801'. Pumped 500 overnight. overnight. ns gelled 15% iron control gallons fresh water. Unset H and lay down 2-7/8" work- tic coated tubing. Removed uid and set packer at 8822'. esia, but did not witness.
12. Describe Proposed or Completed work) SEE RULE 1103. 6-26-96 - Moved in Unset packer. TOO 6-27-96 - TIH with tubing and bailer. gallons of xylene 6-28-96 - Acidized acid and ball seal packer and dropped string. 6-29-7-1-96 - TIH BOP and nippled up Tested annulus to Released well to p I hereby certify that the information abov SKONATURE TYPE OR PRINT NAME Rusty K	and rigged up pulling up OH and lay down 8800' of a bailer and 2-7/8" tubing TIH with packer and 2-7 down 2-7/8" tubing. Shut l perforations 8902-9062' lers. Flushed and overflu d down thru perfs to knock with nickel plated packer o wellhead. Loaded annulu 600 psi for 30 minutes. oroduction.	OTHER: Acidize i and give pertinent dates, include off. Nippled dow corroded 2-7/8" p g to 9103'. Cais 7/8" tubing. Set well in to soak with 15000 gallo ished with 20000 c balls off. TOO c and 2-7/8" plas is with packer fl Notified OCD-Art	njection perforations X ing estimated date of starting any proposed In wellhead and installed BOP. lastic coated tubing. ng had no fill. TOOH with packer at 8801'. Pumped 500 overnight. ns gelled 15% iron control gallons fresh water. Unset H and lay down 2-7/8" work- tic coated tubing. Removed uid and set packer at 8822'. esia, but did not witness. echnician DATE July 8, 1996
12. Describe Proposed or Completed work) SEE RULE 1103. 6-26-96 - Moved in Unset packer. TOO 6-27-96 - TIH with tubing and bailer. gallons of xylene 6-28-96 - Acidized acid and ball seal packer and dropped string. 6-29-7-1-96 - TIH BOP and nippled up Tested annulus to Released well to p I hereby certify that the information abov SKONATURE TYPE OR PRINT NAME Rusty K	and rigged up pulling up OH and lay down 8800' of a bailer and 2-7/8" tubing TIH with packer and 2-7 down 2-7/8" tubing. Shut l perforations 8902-9062' lers. Flushed and overflu d down thru perfs to knock with nickel plated packer o wellhead. Loaded annulu 600 psi for 30 minutes. oroduction.	OTHER: Acidize i and give pertinent dates, include off. Nippled dow corroded 2-7/8" p g to 9103'. Cais 7/8" tubing. Set twell in to soak with 15000 gallo ished with 20000 t balls off. TOO c and 2-7/8" plas is with packer fl Notified OCD-Art	njection perforations X ing estimated date of starring any proposed In wellhead and installed BOP. lastic coated tubing. ng had no fill. TOOH with packer at 8801'. Pumped 500 overnight. Ins gelled 15% iron control gallons fresh water. Unset H and lay down 2-7/8" work- tic coated tubing. Removed uid and set packer at 8822'. esia, but did not witness. Echnician DATE July 8, 1996 TELEPHONE NO. 505/748-1