

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-00221
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Flint GU	
8. Well No.	4
9. Pool name or Wildcat	Undesignated San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3336' DF - 3323' GL	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>22</u> Township <u>18S</u> Range <u>26E</u> NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3336' DF - 3323' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CCMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Abandon Yeso & recomple to San Andres <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-18-95 - Moved in and rigged up pulling unit. TOOH with rods and pump. Nippled up 21-1995  
BOP. TOOH with tubing. TIH with bridge plug and set bridge plug at 2600'. TOOH with  
setting tool and rigged down wireline. Tested casing to 3000 psi, OK. Shut down.  
7-19-95 - TIH with 4" casing guns and perforated 1755-1779' w/25 .42" holes (1 SPP).  
TOOH with casing guns. TIH w/packer and tubing to 1795'. Spot 2 bbls 20% NEFE acid across  
perforations 1755-1779'. Moved up and set packer at 1633'. Acidized perforations 1755-79'  
with 3000 gallons 20% NEFE acid and ball sealers. Unset packer at 1633'. TOOH with tubing  
nad packer. Nippled down BOP. Rigged up frac valve. Shut down.  
7-20-95 - Frac'd perforations 1755-1779' (down 5-1/2" casing) with 100000 gallons 30# cross-  
link gel and 300000# 20-40 Brady sand. Opened up for forced closure. Flow well back.  
Shut down.  
7-21-95 - Bled well down. Nippled down frac valve. Installed BOP. TIH with 2-7/8"  
tubing to 2000'. Reverse circulate casing clean. TOOH with tubing. Released well to  
production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE July 28, 1995  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

APPROVED BY

TITLE

DATE

AUG 2 1995

CONDITIONS OF APPROVAL, IF ANY: