

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
112 Fe, New Mexico 87504-2088

WELL API NO.

30-015-00256

Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL WELL ☐

GAS WELL ☒

OTHER

2. Name of Operator

Chi Operating, Inc.

3. Address of Operator

4. Well Location

Unit Letter J : 1980 Feet From The South

Line and 1986

Feet From The East Line

Section 29

Township 18 S

Range 26 E

CD ARTESIA NM PM

Eddy

County

10. Elevation (Show whether DF, REB, BT, GR, etc.)

6 L 3916

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1) Minu P & A Equipment

35' cent on CIBP Tag

2) Spot 55 SXS at 8900' WOC + TAG or CIBP @ 8900 w/10sx

3) Load Hole with 9.5 lb/gal mud.

6300' w/10 sx

4) Spot 50 SXS at 6300' WOC + TAG on CIBP @ 6300 w/10sx

5) Determine Free point of 7" csg. and Cut.

6) Pull 7" casing (4000' +)

7) Spot 45 SXS on 7" csg. Stub, WOC + TAG *100' cent plug 2347

8) Spot 60 SXS at 1557 - across - across shoe plug - TAG

9) Spot 10 SXS Surface, Plug, Count, Weld on Dry Hole Marker, Back Fill Pit & Cement 20'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

John W. Qualls

TITLE

Operations Manager

DATE

1-19-98

TYPE OR PRINT NAME

John W. Qualls

TELEPHONE NO. 915-685-5001

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

JAN 27 1998

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: