

N. M. O. C. C. COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM 0537370
Bureau No 42 R1424
LEASE LOCATION AND SERIAL NO
~~16-050165~~
IF INDIAN, ALLOTTEE, OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ 2. NAME OF OPERATOR Amoco Production Company 3. ADDRESS OF OPERATOR BOX 68, HOBBS, N. M. 88240 4. LOCATION OF WELL (Report location clearly and in accordance with any State or Federal law. See also space 17 below.) At surface 330' FSL x 1650' FEL Sec. 34 (Unit 0, SW/4 SE/4) 14. PERMIT NO.		RECEIVED MAY 22 1973 O. C. C. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3626' R. D. B.		7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME HARBOLD Fenzal 9. WELL NO. 1 10. FIELD AND POOL, OR WELDCAT EMPIRE PADDOCK 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 34-17-27 NMPM 12. COUNTY OR PARISH EDDY 13. STATE N.M.	
---	--	--	--	---	--

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well has declined below its economic limit to produce. No work over possibilities. Propose to P+ A as follows:

Spot 25 on cement plug from PBD 3088 - 2700' (Perfs 3086 - 3075')

Shoot & Pull 4 1/2" casing from above 2650'.

Spot 30 on cement plug in & out of 4 1/2" stub.

Spot 35 on " " " " " 8 5/8" shoe 1480'.

Spot 10 on " @ surface & erect P+ A marker

all intervals to be filled w/ 25# gel/bx mud

Make final cleanup and level location

TD- 5697
PBD- 3088

18. I hereby certify that the foregoing is true and correct

SIGNED _____	TITLE AREA SUPERINTENDENT	DATE 5-10-73
--------------	---------------------------	--------------

(This space for Federal or State office use)

APPROVED BY _____	TITLE _____	DATE _____
-------------------	-------------	------------

CONDITIONS OF APPROVAL, IF ANY:

044- USGS-A
1- DIV
1- SUSP
1- ARCO-MIDLAND
1- PRU

APPROVED

MAY 21 1973

R. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED
MAY 15 1973
GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO