

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. D. Dist. 2
1301 N. Grand Avenue
Alamogordo, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

CISF

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

ARCO Permian

3. Address and Telephone No.

P.O. Box 1089, Eunice, NM 88231

505-394-1649

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

J, 1980' FSL & 1980' FEL

Sec. 1-T18S-R27E

5. Lease Designation and Serial No.

NM016788

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8910138010

8. Well Name and No.

Empire Abo Unit "K" 19

9. API Well No.

30-015-00696

10. Field and Pool, or exploratory Area

Empire Abo

11. County or Parish, State

Eddy

NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TD: 6180' PBD: 6178' ELEV: 3643' KB CIBP: 6130' PERFS: 6042-6060', 5926-6000'

MIRUPU. NDWH. NUBOP. RU WL unit.

RIH w/SV & set in SN @ 5865'. POH

GIH & chem cut 2-3/8" tbg in 2nd jt. above pkr.

POH w/WL & Chem cutter. RDWL unit.

POH w/tbg.

GIH w/overshot, SN, & 2-3/8" WS to top of fish.

Swab well dn to SN. If well begins to flow kill well w/1 bbls 2% KCL wtr.

GIH catch fish. RIs pkr. POH.

RIH w/bull plugged MA, perf sub, SN & 2-3/8" tbg. Land SN @ +/- 6060'.

NDBOP. NUWH. Swab for test. RDP. RTP.

APPROVED

JAN - 10 2002

LES BABYAK
PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct

Signed Russell D. Murish

Title Sr. Administrative Assistant

Date 01/08/02

(This space for Federal or State office use)

Approved by _____

Title _____

Date _____

Conditions of approval, if any:

RECEIVED
JUL 9 1966
U.S. AIR FORCE
SOUTHWEST REGION
PORTLAND, ORE