

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-015-00717</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>06-693</b>
7. Lease Name or Unit Agreement Name <b>EMPIRE ABO UNIT "K"</b>
8. Well No. <b>16</b>
9. Pool name or Wildcat <b>EMPIRE ABO</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator <b>ARCO Permian</b>
3. Address of Operator <b>P.O. BOX 1610, MIDLAND, TX 79702</b>	4. Well Location Unit Letter <b>I</b> : <b>1980</b> Feet From The <b>SOUTH</b> Line and <b>660</b> Feet From The <b>EAST</b> Line Section <b>2</b> Township <b>18S</b> Range <b>27E</b> NMPM <b>EDDY</b> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3574 RKB</b>	

11.

**Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: **DRILL HORIZONTAL EXTENSION** ☒

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**PROPOSE TO DRILL HORIZONTAL EXTENSION AS FOLLOWS:**

1. POH W/ CA.
2. SQZ EXISTING ABO PERF 6072-6086.
3. WOC. DO CMT & PRESS TEST.
4. MILL OUT CSG F/5995-6055.
5. SPOT KICK OFF PLUG F/6089 PBD-5600.
6. WOC. DO CMT TO 5995.
7. DRILL SHORT RADIUS CURVE & 500'+ HORIZONTAL EXTENSION.
8. RIH W/CA & RETURN TO PROD.

JAN 13 1995

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken W. Gosnell TITLE AGENT DATE 01-12-95  
TYPE OR PRINT NAME KEN W. GOSNELL TELEPHONE NO. 915 688-5672

(This space for State Use)

APPROVED BY Janice Green TITLE District Supervisor DATE 2/1/95  
CONDITIONS OF APPROVAL, IF ANY: