

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

C157
Op

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-00717

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
06-693

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
EMPIRE ABO UNIT "K"

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
BP America Production Company

8. Well No.
16

3. Address of Operator
P.O. Box 1089, Eunice, New Mexico 88231

9. Pool name or Wildcat
EMPIRE ABO

4. Well Location
Unit Letter I : 1980 Feet From The S Line and 660 Feet From The E Line

Section 2 Township 18S Range 27E NMPM EDDY County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3574' RKB

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Workover ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6101' CIBP: 6000' PERFS: HORIZONTAL OH 6039-6813', 6030-6086' Squeezed off, 5560-5952' new perfs

04.08.02: MIRUPU. POH w/rods & pmp. NDWH. NUBOP.

04.09.02: TOH w/tbg. TIH w/bit, scraper, testing tbg to 5000# psi below slips to 6010'.

04.10.02: Set CIBP @ 6000' & perf 5560-63', 5566-90', 5602-06', 5610-18', 5622-26', 5638-42', 5646-51', 5678-83', 5688-96', 5700-34', 5738-60', 5766-71', 5787-90', 5806-11', 5884-92', 5896-5908', 5942-52', 2 JSPF. TIH w/pkr to 5987'.

04.12.02: Spot 500 gals 15% HCL. PU to 5457' set pkr & pmp 4500 gals 15% HCL. Rls pkr. TOH. TIH w/collar & bailer.

04.15.02: Clean out frac balls.

04.16.02: RIH w/2-3/8" tbg. Set @ 5957'. NDBOP. Set TAC @ 5551'. SN @ 5958'. NUWH. Return well to prodction. n 24 hrs produced 12 bo, 16 bw, 376 mcf.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 06.06.02

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY Record TITLE Record DATE JUN 12 2002

CONDITIONS OF APPROVAL, IF ANY: